



***Noted:***

**28A Asbestos Management Plan**

- 28A.1 In response to queries from a UCU representative, the Safety Manager (Construction, Maintenance and Fire) had removed the lower risk reference from item 5.4.3 and specifically stated the items that would be monitored biannually.
- 28A.2 The UCL Asbestos Management Plan document had recently been updated to reflect the new Control of Asbestos Regulations 2012. It is now revision 5. The changes to the document were minor as the principal duties have remained the same under the new legislation.
- 28A.3 In practice the changes meant that some types of non-licensed work with asbestos would



32.5 Regarding point 13 of the UCL Safety Standard, a Unite representative enquired if the

